



## Recycling Load Inspection

Recology King County  
7 S. Idaho St., Seattle, WA 98134  
(206) 767-1166

No.  
01637  
Date  
02/21/2019  
Time  
08:30 AM

### Source Information

Overall Load Condition* <b>GOOD</b>	Truck Type Compactor / Roll Off	City Seattle	Truck No. 12322	Auditor Name K. HARRIS
Customer COLUMBIA BUILDING	Address 1313 E COLUMBIA ST	Svc. Code 40CPRNC	Account No. 2000773	

### Contaminants Observed

- |  |  |  |
|--|--|--|
| <input type="checkbox"/> Mixed / Bagged Refuse                   | <input type="checkbox"/> Diapers / Pet Waste | <input type="checkbox"/> PLA (Bio-Plastics)            |
| <input checked="" type="checkbox"/> Film Plastics / Plastic Bags | <input type="checkbox"/> Latex Gloves        | <input checked="" type="checkbox"/> C&D Debris         |
| <input type="checkbox"/> Soiled Paper                            | <input type="checkbox"/> Yard Waste / Wood   | <input type="checkbox"/> Electronics / Universal Waste |
| <input type="checkbox"/> Wax Cardboard                           | <input type="checkbox"/> Foam                | <input type="checkbox"/> Chemicals / Paint             |
| <input type="checkbox"/> Food Waste                              | <input type="checkbox"/> Packaged Food       | <input type="checkbox"/> HAZ Waste                     |
| <input type="checkbox"/> Liquids / Saturation                    | <input type="checkbox"/> Textiles/Fabrics    | <input type="checkbox"/> Other (see notes)             |

#### Notes

12 bags opened, 1 water hose overall load looked excellent.

### Photos



#### Load Condition Parameters\*

GOOD (0-1% contamination volume, 0-1 filled bags, 0-5 loose contaminants)  
ACCEPTABLE (2-5% contamination volume, 0-3 filled bags, 5-10 loose contaminants)  
MARGINAL (5-10% contamination volume, 3-5 filled bags, 10-20 loose contaminants)  
UNACCEPTABLE (+10% contamination volume, 5+ filled bags, 20+ loose contaminants)

d3e6ddcc8ac73ebb-1550766638805